

PEOC ERRATA TO REPLY TO BOARD IR
May 18, 2005

Board Staff Information Requests for Paramount Energy Operating Corp. (Paramount)

Note changes to Tables 2 and 4 on pages 4 and 5 respectively, of the PEOC reply to the Board IR.

The changed information is highlighted and underlined for PEOC porosity and permeability values. These tables replace Table 2 and Table 4 in the original document submitted to the Board Staff.

Well: 11-30-80-6W4

Layer	Chard Poro	Revised PEOC Poro	Chard Perm	Revised PEOC Perm	PEOC Kv
Top Water	0.30	<u>0.34</u>	1000	<u>2573</u>	<u>1303</u>
Bitumen Zone	0.30	<u>0.31</u>	1000	<u>607</u>	<u>315</u>
Bitumen Pay 1	0.30	<u>0.32</u>	1000	<u>1504</u>	<u>981</u>
Bitumen Pay 2	0.32	<u>0.31</u>	2000	<u>759</u>	<u>427</u>
Bitumen Pay 3	0.35	<u>0.34</u>	5000	<u>1689</u>	<u>1469</u>

Table 1: EUB-4

Well: 11-30-80-6W4

Layer	Chard Breakthru Poro	Revised PEOC Poro	Chard Breakthru Perm	Revised PEOC Perm	PEOC Kv
Top Water	0.30	<u>0.34</u>	1000	<u>2573</u>	<u>1303</u>
Bitumen Zone	0.30	<u>0.31</u>	1000	<u>607</u>	<u>315</u>
Bitumen Pay 1	0.30	<u>0.32</u>	2000	<u>1504</u>	<u>981</u>
Bitumen Pay 2	0.32	<u>0.31</u>	5000	<u>759</u>	<u>427</u>
Bitumen Pay 3	0.35	<u>0.34</u>	5000	<u>1689</u>	<u>1469</u>

Table 2: EUB-4